

External Power Supply

12 volt

- **90G000008** Cable, **RS-232**, 9P, Female, Straight, CAB-327, Requires External Power, 6 ft.
- **90A052361** Cable, **USB**, Type A, External Power, High Current, PVCW, Straight, **1.2M**, Black
- **90A052356** Cable, **USB**, Type A, External Power, High Current, PVCW, Straight, **3M**, Black
- **8-0935** Power Adapter, 12V DC, AC/DC Regulated, RoHS (Requires Power Cord - 6003-XXXX)
- **6003-0940** Power Cord, AC, IEC/EU

5 volt

- **90G000008** Cable, **RS-232**, 9P, Female, Straight, CAB-327, Requires External Power, 6 ft.
- **90ACC0287** Power Supply, 5VDC, includes 2 pin power cord adapter.
- **90ACC1885** Power Cord, 2-Pin, EU

USB cable with external power supply

Below is the codes and description of the cable needed to bring additional power to the WLC4x90 cradle, or to certain other scanners such as the PD9531-HPE that requires 10-30 volt

Code product: 8-0935

Description: Power Adapter, 12V DC, AC/DC Regulated, RoHS (Requires Power Cord - 6003-XXXX depending on the country where it will be used)

Code: 6003-0924

Description: Power Cord, 220V, Italy/Chile

Product code: 90A052361 Cable, USB, Type A, External Power, High Current, PVCW, Straight, 1.2M, Black (for use with WLC4X90 Wireless Charging Base Station PD9531HPE 10-30 volt)

Product code: 90A052356 Cable, USB, Type A, External Power, High Current, PVCW, Straight, 3M, Black (for use with WLC4X90 Wireless Charging Base Station and Powerscan PD9531HPE 10-30 volt)